

Surry 2

2Q/2005 Plant Inspection Findings

Initiating Events

Mitigating Systems

Significance:  Jun 30, 2005

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to Promptly Correct High Vibrations on a Safety Injection Pump

The inspectors identified a non-cited violation of 10CFR50, Appendix B, Criterion XVI, "Corrective Action" for failure to promptly correct a condition adverse to quality. The licensee identified, but did not promptly correct, the high vibration condition on the Unit 2 'B' safety injection pump, 2-SI-P-1B. The issue was identified in April 2002 but was not corrected until October 2004.

The finding was determined to be more than minor because it affected the Mitigating Systems Cornerstone objective to ensure the availability, reliability, and capacity of systems that respond to initiating events to prevent undesirable consequences. The finding was associated with the equipment performance and human performance attributes of the cornerstone. The finding affects the Mitigating Systems Cornerstone function of core decay heat removal and is of low safety significance (Green) because it did not result in the loss of a safety function of a single train for greater than the Technical Specification allowed outage time and is not risk significant in response to external events. The finding is also related to the cross-cutting area of identification and resolution of problems because the cause of the vibration condition was not promptly identified and corrected by the licensee.

Inspection Report# : [2005003\(pdf\)](#)

Significance:  Jun 30, 2005

Identified By: NRC

Item Type: NCV NonCited Violation

Inadequate Corrective Action Resulting in Recurring Thru-wall Leaks on Main Control Room Chillers '4D' and '4E'

The inspectors identified a non-cited violation of 10 CFR 50, Appendix B, Criterion XVI, "Corrective Action" for failure to prevent recurrence of a condition adverse to quality. The licensee identified but did not take corrective actions to prevent recurrence of thru-wall leaks in service water related components on main control room chillers '4D' and '4E'. At least 11 thru-wall leaks have occurred between June 1995 and February 2005 without proper corrective actions to address the cause.

The finding was determined to be more than minor because it affects the Mitigating Systems Cornerstone objective of ensuring the availability, reliability, and capability of systems that respond to initiating events to prevent undesirable consequences. The finding is associated with the equipment performance and design control attributes of the cornerstone. The finding affects the Mitigating Systems Cornerstone function of core decay heat removal and is of low safety significance (Green) because it did not result in the loss of a safety function of a single train for greater than the Technical Specification allowed outage time and is not risk significant in response to external events. The finding is also related to the cross-cutting area of identification and resolution of problems because corrective actions were not taken to prevent recurrence of the flow accelerated corrosion condition.

Inspection Report# : [2005003\(pdf\)](#)

Significance:  Mar 31, 2005

Identified By: NRC

Item Type: FIN Finding

Failure to Provide a Power Supply for Turbine Building Flood Instrumentation and Circulating Water Condenser Inlet Valve Logic Which Would be Available Following a Loss of offsite power

The inspectors identified a finding in that the turbine building flood control system did not provide adequate protection for all licensing basis flooding scenarios. Specifically, portions of the flooding detection and mitigation circuitry, turbine building flood level detection instrumentation, and circulating water (CW) condenser inlet valve closure logic, would not be available for some flooding scenarios involving a loss of offsite power. The licensee's completed corrective actions include installation of a design change which provides redundant, vital bus powered detection and warning of flooding in the turbine building basement which alarms in the control room.

The finding is greater than minor because it affects the design control attribute of the mitigating systems cornerstone objective. A Phase 3 risk analysis determined that this finding was of very low safety significance. This was primarily due to the low frequency of an earthquake of

sufficient magnitude to fail offsite power and the circulating water piping connected to the condenser, but of insufficient magnitude to cause catastrophic failure of the turbine building. (Section 40A5.2)

Inspection Report# : [2005002\(pdf\)](#)

Significance: N/A Dec 10, 2004

Identified By: NRC

Item Type: FIN Finding

95002 Supplemental Inspection Results for Degraded Mitigating Systems Cornerstone

This supplemental inspection was performed by the NRC to assess the licensee's problem identification, root cause evaluation, extent of condition determination, and corrective actions associated with a White performance indicator (PI) and a White inspection finding. These two issues, which were in the Mitigating Systems Cornerstone, placed the performance of Surry Units 1 and 2 in the Degraded Cornerstone Column of the NRC's Action Matrix for the first quarter 2004. The PI, Safety System Unavailability - Emergency AC Power, crossed the threshold from Green to White in the fourth quarter 2001 for both units and remained through the first quarter 2004 for Unit 2, and through the third quarter 2004 for Unit 1. The White PI was evaluated in Supplemental Inspection Report 05000280,281/2002008. The White inspection finding involved Surry fire response procedures that were not effective in ensuring safe shutdown for a fire in Emergency Switchgear and Relay Room Numbers 1 or 2, of Surry Power Station Units 1 and 2 respectively. Specifically, the procedures may not have precluded an extended loss of reactor coolant pump (RCP) seal injection flow, resulting in an RCP seal loss of coolant accident. The performance issue associated with this inspection finding was previously characterized as having low to moderate risk significance (White) in NRC "Final Significance Determination" letter dated September 15, 2004.

During this supplemental inspection, which was performed in accordance with Inspection Procedure 95002, the inspectors utilized the results from Supplemental Inspection Report 05000280,281/2002008 to address the White PI, Safety System Unavailability - Emergency AC Power. The combined assessment of the White PI and the White inspection finding that resulted in the degraded Mitigating Systems cornerstone is summarized below.

As indicated in Supplemental Inspection Report 05000280,281/2002008, the licensee's formal root cause evaluations (RCE) for the White PI, Safety System Unavailability - Emergency AC Power, was acceptable. The licensee implemented adequate corrective actions to prevent recurrence based upon their RCEs.

The licensee performed a Category 1 RCE, S-2003-1490, to address the fire response procedure finding associated with restoration of seal injection flow to the RCPs. This RCE was considered by the inspectors to be independent and consistent with the prescribed charter. However, the inspectors noted that the licensee's extent of condition reviews lacked thoroughness with regard to the RCE findings. Additionally, the licensee performed Common Cause Evaluation (CCE) S-2004-1504 in January 2004 to assess Surry Power Station Units 1 and 2 performance in the NRC's Reactor Oversight Process. The licensee also performed CCE S-2004-3295 in October 2004 to address the degraded Mitigating Systems cornerstone for Surry Units 1 and 2. The inspectors considered that, although CCE S-2004-3295 did not possess the attributes of an extent of condition evaluation, this CCE determined, through review of various corrective action system documents, that there was a common cause for these White issues. During this 95002 supplemental inspection, the licensee performed more comprehensive extent of condition related actions through additional reviews of external information programs and processes, and reviews of various management committees' charters/procedures for dispositioning technical concerns. These additional extent of condition and extent of cause related reviews, combined with the efforts in CCE S-2004-3295, were considered to be appropriately focused based on the inspectors' independent extent of condition review.

Although corrective actions appeared to be appropriately prioritized and tracked, the inspectors noted that the licensee was still evaluating long-term corrective action options for resolving the White inspection finding related to restoration of RCP seal injection flow. Consequently, the licensee had not identified all of the corrective actions for this finding and a completion date was not available. Overall, corrective actions related to this White inspection finding adequately addressed compliance restoration and the identified root causes and causal factors. While the inspectors considered that the appropriate root causes were identified by the licensee in RCE S-2003-1490, the contributing cause identified in this RCE was not considered to be the most appropriate. Specifically, the licensee identified that the failure to install Westinghouse (W) high temperature O-rings in the RCP seals in a timely manner was a contributing cause to the failure to revise the Surry Fire Contingency Action (FCA) procedures once the difference between the FCAs and the emergency response guidelines (ERG) was identified. The inspectors noted that the RCE did not recommend any corrective actions for this identified contributing cause. However, the inspectors considered that this contributing cause identified in the RCE was not the most appropriate one. The inspectors considered that the more appropriate contributing cause should have been the unclear responsibilities and inaccurate perception of who had ownership of the FCA procedures. This determination was based on the inspectors' review of RCE S-2003-1490, Potential Problem Report (PPR) 2000-004, and the meeting minutes of the Management Problem Review Team (MPRT) related to PPR 2000-004. The inspectors noted that the licensee had implemented corrective actions to address ownership of the FCA procedures by revising Virginia Power Administrative Procedure (VPAP)-0502, Procedure Process Control.

Inspection Report# : [2004011\(pdf\)](#)

Barrier Integrity

Emergency Preparedness

Occupational Radiation Safety

Significance:  Sep 25, 2004

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to implement and maintain a respiratory protection program that includes written procedures regarding training of respirator users in the change out of SCBA air cylinders

The inspectors identified a violation of 10 CFR 20.1703(c)(4)(ii) which requires the licensee to implement and maintain a respiratory protection program that includes written procedures regarding training of respirator users. In addition, this was related to the emergency planning standards of 10 CFR 50.47(b) (10). Specifically, procedures were not in place to ensure that all Control Room staff had demonstrated proficiency in changing Self Contained Breathing Apparatus (SCBA) air cylinders during emergencies.

This finding is greater than minor because emergency workers who are required to use respiratory protective equipment are not trained to use that equipment. This finding is of very low safety significance because an adequate number of SCBA qualified plant personnel/staff, which were designated emergency responders, would have been available to respond in the event of an actual emergency.

Inspection Report# : [2004004\(pdf\)](#)

Public Radiation Safety

Physical Protection

[Physical Protection](#) information not publicly available.

Miscellaneous

Last modified : August 24, 2005