

Byron 2

4Q/2013 Plant Inspection Findings

Initiating Events

Significance:  Dec 31, 2013

Identified By: NRC

Item Type: NCV NonCited Violation

Reactor Vessel Design Documents Not Updated to Reflect Unit 2 Missing Head Stud

Inspectors identified a finding of very low safety significance and an associated NCV of 10 CFR 50, Appendix B, Criterion III "Design Control" for failure to maintain reactor vessel design specification and analysis up-to-date for the 53 stud vessel head configuration applicable to Unit 2. Specifically, the reactor vessel Design Specification and Design Analysis did not reflect the modified and stuck stud no. 11. The licensee entered this issue into their corrective action program (CAP) as Action Report (AR) 01578285.

The inspectors determined that the performance deficiency was more than minor because it was associated with the Design Control attribute of the Initiating Events Cornerstone and adversely impacted the cornerstone objective of to limit the likelihood of those events that upset plant stability and challenge critical safety functions. The inspectors also answered "Yes" to the More-than-Minor screening question "If left uncorrected, would the performance deficiency have the potential to lead to a more significant safety concern?" Specifically, the inspectors determined that this issue was more than minor because, if left uncorrected, the failure to maintain the Unit 2 reactor vessel design specification and analysis caused them to be inaccurate and if these documents were subsequently relied on for future design changes, the vessel design may not be adequate to maintain structural integrity during design basis events resulting in a loss-of-coolant-accident. The inspectors performed a Phase 1 Significance Determination Process Screening, and evaluated this issue by application of questions 1 and 2. Questions No's 1 and 2 asked: if after a reasonable assessment of degradation, could the finding result in exceeding the reactor coolant system leak rate for a small loss-of-coolant accident (LOCA) or could the finding have likely affected other systems used to mitigate a LOCA resulting in a total loss of their function (e.g., Interfacing System LOCA)? In this case, the degradation prompting the reduction in the number of head studs and the licensee's failure to maintain the design analysis had not yet affected the ability of the reactor vessel to perform its design functions so the inspector answered these questions "No" and this issue screened as having very low risk significance. Inspectors determined that this finding is not indicative of current performance and no cross-cutting aspect was assigned.

Inspection Report# : [2013005](#) (*pdf*)

Significance:  Dec 31, 2013

Identified By: NRC

Item Type: NCV NonCited Violation

Corrosion Effects on the Unit 2 Reactor Vessel Not Monitored

Inspectors identified a finding of very low safety significance and an associated NCV of 10 CFR 50, Appendix B, Criterion III "Design Control" for failure to maintain reactor vessel design specification and analysis up-to-date for the 53 stud vessel head configuration applicable to Unit 2. Specifically, the reactor vessel Design Specification and Design Analysis did not reflect the modified and stuck stud no. 11. The licensee entered this issue into their corrective action program (CAP) as Action Report (AR) 01578285.

The inspectors determined that the performance deficiency was more than minor because it was associated with the Design Control attribute of the Initiating Events Cornerstone and adversely impacted the cornerstone objective of to

limit the likelihood of those events that upset plant stability and challenge critical safety functions. The inspectors also answered “Yes” to the More-than-Minor screening question “If left uncorrected, would the performance deficiency have the potential to lead to a more significant safety concern?” Specifically, the inspectors determined that this issue was more than minor because, if left uncorrected, the failure to maintain the Unit 2 reactor vessel design specification and analysis caused them to be inaccurate and if these documents were subsequently relied on for future design changes, the vessel design may not be adequate to maintain structural integrity during design basis events resulting in a loss-of-coolant-accident. The inspectors performed a Phase 1 Significance Determination Process Screening, and evaluated this issue by application of questions 1 and 2. Questions No’s 1 and 2 asked: if after a reasonable assessment of degradation, could the finding result in exceeding the reactor coolant system leak rate for a small loss-of-coolant accident (LOCA) or could the finding have likely affected other systems used to mitigate a LOCA resulting in a total loss of their function (e.g., Interfacing System LOCA)? In this case, the degradation prompting the reduction in the number of head studs and the licensee’s failure to maintain the design analysis had not yet affected the ability of the reactor vessel to perform its design functions so the inspector answered these questions “No” and this issue screened as having very low risk significance. Inspectors determined that this finding is not indicative of current performance and no cross-cutting aspect was assigned.

Inspection Report# : [2013005](#) (*pdf*)

Significance:  Dec 31, 2013

Identified By: NRC

Item Type: NCV NonCited Violation

Inadequate Vessel Stress Analysis for Unit 2 Missing Head Stud

Inspectors identified a finding of very low safety significance and an associated NCV of 10 CFR 50, Appendix B, Criterion III “Design Control” for failure to perform an adequate thermal-mechanical analysis to support operation with a missing Unit 2 head stud. Specifically, the licensee did not perform a complete set of analysis under operating, faulted and design conditions to confirm the associated stud and flange stresses remained within the Code allowable limits. Consequently, the licensee did not recognize that the bearing stress under the head stud nuts at the vessel flange face exceeded the Code allowable stress. The licensee entered this issue into their CAP as IR 01578717.

The inspectors determined that the performance deficiency was more than minor because it was associated with the Design Control attribute of the Initiating Events Cornerstone and adversely impacted the cornerstone objective of to limit the likelihood of those events that upset plant stability and challenge critical safety functions. The inspectors also answered “Yes” to the More-than-Minor screening question “If left uncorrected, would the performance deficiency have the potential to lead to a more significant safety concern?” Specifically, the inspectors determined that this issue was more than minor because, if left uncorrected, the failure to perform an adequate thermal-mechanical analysis, could result in the inability of the reactor vessel to meet the design basis operating transient without a LOCA. The inspectors performed a Phase 1 Significance Determination Process Screening and evaluated this issue by application of questions 1 and 2. Questions 1 and 2 asked if; after a reasonable assessment of degradation, could the finding result in exceeding the reactor coolant leak rate for a small loss-of-coolant-accident (LOCA) or could the finding have likely affected other systems used to mitigate a LOCA resulting in a total loss of their function (e.g., Interfacing System LOCA)? In this case, because of the available margins in the flange material strength, the inspector answered these questions “No” and this issue screened as having very low risk significance. This finding has a cross-cutting aspect in the area of Human Performance Resources, because the licensee did not have complete, accurate and up-to-date design documentation, procedures, and work packages. Specifically, the licensee failed to ensure the applicable ASME Code Section III design limit for bearing stress (design basis) was correctly translated into a design document (EC 379850). (H.2(c)).

Inspection Report# : [2013005](#) (*pdf*)

Significance:  Sep 27, 2013

Identified By: NRC

Item Type: NCV NonCited Violation

INADEQUATE IDENTIFICATION OF FIRE CURTAIN SPRINKLER DEGRADATION FOR AN AUXILIARY BUILDING STAIRWELL

The inspectors identified a finding of very low safety significance and an associated NCV of Byron Operating License (OL) Condition 2.C.6 for Unit 1 and 2.E for Unit 2 when licensee personnel failed to identify that a fire sprinkler curtain on Elevation 346' had degraded. Specifically, a ball valve had a twisted stem, which had the effect of indicating that an isolation valve was fully open, when in fact it was significantly closed. As part of their immediate corrective actions, the licensee declared the auxiliary building Elevation 346' fire curtain inoperable and initiated compensatory measures that included fire watches until the isolation valve stem was replaced. The licensee entered this issue into their CAP as IR 1560667, "Adverse Trend in Main Drain Results for 346 AB [Auxiliary Building] Sprinkler System."

The performance deficiency was determined to be more than minor because it was associated with the External Factors attribute of the Initiating Events cornerstone and adversely affected the cornerstone objective of limiting the likelihood of those events that upset plant stability and challenge critical safety functions during shutdown as well as power operations. The inspectors determined that the finding could be evaluated using the SDP in accordance with IMC 0609, Appendix F, "Fire Protection Significance Determination Process," because it was associated with fire protection defense-in-depth strategies involving fire confinement. The inspectors determined that while flow to the sprinkler heads was significantly degraded, because less than 10 percent of the heads were obstructed or fouled, and no adjacent heads were fouled, the water curtain had a low degradation rating in accordance with IMC 0609, Appendix F, Attachment 2. Therefore, in accordance with IMC 0609, Appendix F, Attachment 1, Step 1.3.1.B, the finding was determined to be of very low safety significance (Green). This finding had a cross-cutting aspect in the CAP component of the PI&R cross-cutting area (P.1.(a)), because licensee personnel twice failed to identify the degraded sprinkler curtain and when NRC personnel identified the issue and informed licensee personnel, the issue was not entered into the licensee's CAP in a timely manner.

Inspection Report# : [2013007](#) (pdf)

Mitigating Systems

Significance:  Dec 31, 2013

Identified By: NRC

Item Type: NCV NonCited Violation

Emergency Service Water Blowdown Isolation Valves Were Not Tested

The inspectors identified a finding of very low safety significance and associated Non-Cited Violation of 10 CFR Part 50, Appendix B, Criterion XI, "Test Control," for failure to demonstrate the ability to isolate the emergency service water blowdown as credited in analysis described in the Updated Final Safety Analysis Report. Specifically, the licensee was not periodically testing the active function of the blowdown isolation valves. This finding was entered into the licensee's Corrective Action Program, in part, to periodically test the closing function of the blowdown isolation valves.

The performance deficiency was determined to be more than minor because it was associated with the Mitigating Systems cornerstone attribute of equipment performance and affected the cornerstone objective of ensuring the availability, reliability, and capability of the ultimate heat sink to respond to initiating events to prevent undesirable consequences. The finding screened as of very low safety significance because it did not result in the loss of operability or functionality. Specifically, the licensee reviewed recent history of the affected piping system and determined it opportunistically cycled the valves without incidents. The inspectors did not identify a cross-cutting

aspect associated with this finding because it was not confirmed to reflect current performance due to the age of the performance deficiency.

Inspection Report# : [2013005](#) (pdf)

Significance:  Dec 31, 2013

Identified By: NRC

Item Type: NCV NonCited Violation

Intake Structure Silt Level Acceptance Criteria Were Non-Conservative

The inspectors identified a finding of very low safety significance and associated Non-Cited Violation of 10 CFR Part 50, Appendix B, Criterion III, "Design Control," for failure to develop appropriate intake structure silt level acceptance criteria. Specifically, the licensee used a non-conservative river water low level value as an input when developing silt level acceptance criteria. This finding was entered into the licensee's CAP to correct the acceptance criteria and revise the affected surveillance procedures.

The performance deficiency was determined to be more than minor because it was associated with the Mitigating Systems cornerstone attribute of equipment performance and affected the cornerstone objective of ensuring the availability, reliability, and capability of the ultimate heat sink to respond to initiating events to prevent undesirable consequences. The finding screened as of very low safety significance because it did not result in the loss of operability or functionality. Specifically, a historic review did not find an example where the as-found silt level resulted in an inoperable condition. The inspectors did not identify a cross-cutting aspect associated with this finding because it was not confirmed to reflect current performance due to the age of the performance deficiency.

Inspection Report# : [2013005](#) (pdf)

Significance:  Dec 31, 2013

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to Implement Preventative Maintenance Procedure Replacement Schedules for Essential Service Water Makeup Pump Diesel Engine Hoses

. Inspectors identified a finding of very low safety significance and associated Non-Cited Violation of TS 5.4.1, "Procedures," for failure to establish and implement a preventive maintenance schedule to replace hoses on SX Make Up pump diesel engine. Specifically, the licensee failed to implement preventive maintenance procedures that require periodic replacement of hoses on pre-established schedules in accordance with vendor recommendation and corporate Performance Centered Maintenance (PCM) template. The finding was entered into the licensee's Corrective Actions Program, in part, to evaluate the current maintenance strategy for maintaining flexible hoses on the SX make-up pump diesel engines.

The performance deficiency was determined to be more than minor because if left uncorrected the failure of SX Make up pump engine hoses could result in the inoperability of the SX Make up pumps. The performance deficiency also screened as more than minor because it affected the Procedure Quality attribute of the Mitigating Systems cornerstone and affected the cornerstone objective of ensuring the reliability of systems that respond to initiating events to prevent undesirable consequences. The finding screened as being of very low safety significance because it did not result in the loss of operability or functionality. Specifically, the licensee has reviewed the recent history of hose inspections and instances that required hose replacement and determined no failures have occurred that resulted in an inoperable condition. The inspectors did not identify a cross-cutting aspect associated with this finding because it was not confirmed to reflect current performance due to the age of the performance deficiency.

Inspection Report# : [2013005](#) (pdf)

Significance:  Sep 27, 2013

Identified By: NRC

Item Type: NCV NonCited Violation

FAILURE TO PROPERLY ASSESS OPERABILITY OF THE 2A EDG FOLLOWING POST-MODIFICATION TESTING

The inspectors identified a finding of very low safety significance and an associated NCV of Technical Specification (TS) 3.8.1 when licensee personnel failed to properly assess the operability of the 2A emergency diesel generator (EDG) following a post-maintenance test that rendered the 2A EDG ventilation fan, a credited support system, incapable of performing its auto-start support system function for a period of two days. As part of the licensee's immediate corrective actions, a trip signal that prevented the 2A EDG fan from starting was reset. The licensee entered this issue into their CAP as IR 1252529, "2A DG [EDG] Vent Fan Trip Signal Not Reset."

The performance deficiency was determined to be more than minor because it was associated with the Configuration Control and Human Performance attributes of the Mitigating Systems cornerstone and adversely affected the cornerstone objective of ensuring the availability, reliability, and capability of systems that respond to initiating events to prevent undesirable consequences (i.e., core damage). Specifically, following an August 15, 2011, post-maintenance test of the 2A EDG room ventilation system high differential pressure (D/P) trip time delay, the licensee failed to implement the necessary procedural steps that ensured the high D/P trip signal was reset. This resulted in the 2A EDG room ventilation fan from auto-starting, resulting in the inoperability of the 2A EDG from August 15-17, 2011. The inspectors determined that this finding screened as having very low safety significance (Green) in accordance with IMC 0609, Appendix A, "The Significance Determination Process (SDP) for Findings at Power," Exhibit 2, "Mitigating Systems Screening Questions," as it did not represent an actual loss of function of at least a single train of safety-related equipment for greater than its Technical Specification (TS) allowed outage time and did not represent an actual loss of function of one or more non-TS trains of equipment designated as high safety-significant in accordance with the licensee's maintenance rule program for greater than 24 hours. This issue had a cross-cutting aspect in the Work Practices component of the Human Performance cross-cutting area (H.4(a)), because licensee personnel failed to use appropriate human performance techniques to ensure that work tasks were performed safely and individuals do not proceed in the face of uncertainty.

Inspection Report# : [2013007](#) (pdf)

Significance: G Sep 27, 2013

Identified By: NRC

Item Type: NCV NonCited Violation

ACCEPTANCE CRITERIA FOR BATTERY VOLTAGE IN TS SURVEILLANCE PROCEDURE FAILED TO ACCOUNT FOR TEST EQUIPMENT UNCERTAINTY

The inspectors identified a finding of very low safety significance and an associated NCV of 10 CFR Part 50, Appendix B, Criterion XI, "Test Control," when licensee personnel failed to account for test instrument uncertainty in the acceptance criteria for TS Surveillance procedure 2BOSR 8.6.1-2, "125VDC [Volt Direct Current] ESF [Engineered Safety Feature] Battery Bank and Charger 212 Operability Weekly Surveillance." As part of the licensee's immediate corrective actions, the voltage of the affected battery charger was adjusted. The licensee also planned to perform a fleet-wide evaluation of the issue. The licensee entered this issue into their CAP as IR 0156440, "125 VDC Battery TS Surveillance Values."

The performance deficiency was determined to be more than minor because it was associated with the Equipment Performance attribute of the Mitigating Systems cornerstone and adversely affected the cornerstone objective of ensuring the availability, reliability, and capability of systems that respond to initiating events to prevent undesirable consequences (i.e., core damage). Specifically, the acceptance criteria for the battery voltage did not assure the availability of the safety-related direct current (DC) batteries that would meet the minimum voltage as required by the TSs. This finding screened as having very low safety significance, in accordance with Exhibit 2 of IMC 0609,

Appendix A, “The Significance Determination Process (SDP) for Findings for At-Power,” because it was a design deficiency confirmed not to result in a loss of operability. The inspectors did not identify a cross-cutting aspect associated with this finding because the finding was not representative of current performance. Specifically, the decision to not include the instrument uncertainty was made in 2003, as part of an evaluation for a previously identified issue.

Inspection Report# : [2013007](#) (*pdf*)

Significance:  Jun 30, 2013

Identified By: Self-Revealing

Item Type: NCV NonCited Violation

FAILURE TO ESTABLISH A PROCEDURE TO CONTROL THE SPENT FUEL POOL COOLING SYSTEM

A finding of very low safety significance and an associated NCV of Technical Specification (TS) 5.4.1 was self-revealed when a configuration control error during a local leak rate test (LLRT) resulted in the inadvertent draining of the spent fuel pool (SFP). The licensee entered this issue into their CAP as IR 1506862, “SFP Level Reduced.” Licensee corrective actions included isolating the leak and restoring SFP level to normal.

The inspectors determined that the performance deficiency was more than minor because it was associated with the Human Performance attribute of the Barrier Integrity Cornerstone and adversely impacted the cornerstone objective of providing reasonable assurance that physical design barriers (fuel cladding, reactor coolant system, and containment) protect the public from radionuclide releases caused by accident or events. The finding was screened in accordance with IMC 0609, Attachment 4, “Phase 1 – Initial Screening and Characterization of Findings,” and was determined to be of very low safety significance since the finding was not associated with the loss of cooling to the SFP that would have precluded restoration prior to boiling, a fuel handling error, or loss of SFP inventory below the minimum analyzed level limit specified in the site-specific licensing basis. This finding had a cross-cutting aspect in the Work Practices component of the Human Performance cross-cutting area because operators did not use human error prevention techniques commensurate with the risk of the assigned task nor did personnel stop work in the face of uncertainty (H.4.a).

Inspection Report# : [2013003](#) (*pdf*)

Significance:  Mar 31, 2013

Identified By: NRC

Item Type: FIN Finding

FAILURE TO PROPERLY SCOPE ALL PERTINENT EXTERNAL FLOOD PROTECTION FEATURES INTO WALKDOWN LISTS IN ACCORDANCE WITH INDUSTRY GUIDANCE NEI 12-07

The inspectors identified a finding of very low safety significance (Green) when licensee personnel failed to develop inspection lists that included all external flood protection features credited in current licensing bases (CLB) documents as specified in Nuclear Energy Institute (NEI) 12-07, “Guidelines for Performing Walkdowns of Plant Flood Protection Features.” Specifically, concrete flood barriers in the fuel handling building (FHB) that protected safety-related equipment in the auxiliary building and flood barriers for the spent fuel pool cooling pumps were not included in the licensee’s flooding inspection lists, although these passive components were a critical element of the licensee’s flood mitigation strategy. The licensee entered this issue into their CAP as IR 1466355. Corrective actions included plans to perform an inspection of the NRC-identified features that were omitted from the inspection lists and an extent-of-condition review.

The inspectors determined that the performance deficiency was more than minor because it was associated with the Protection Against External Factors (Flood Hazard) attribute of the Mitigating Systems cornerstone and adversely affected the cornerstone objective of ensuring the availability, reliability, and capability of systems that respond to initiating events to prevent undesirable consequences (i.e., core damage). Because the finding did not involve the loss

or degradation of equipment or function specifically designed to mitigate a seismic, flooding, or severe weather initiating event (e.g., seismic snubbers, flooding barriers, tornado doors), the finding was of very low safety significance (Green). This finding had a cross-cutting aspect in the Work Practices component of the Human Performance cross-cutting area because licensee personnel failed to properly apply human error prevention techniques such as peer checking and proper documentation of activities [H.4(a)].

Inspection Report# : [2013002](#) (*pdf*)

Barrier Integrity

Significance: G Dec 31, 2013

Identified By: NRC

Item Type: NCV NonCited Violation

Analytical Bases for PTL Curves Not Maintained Consistent With Unit 2 Head Stud Configuration

Inspectors identified a finding of very low safety significance and an associated NCV of TS 5.6.6, Reactor Coolant System (RCS) Pressure and Temperature Limits Report (PTLR), for failure to maintain the analytical basis for deriving the pressure temperature limit curves consistent with the Unit 2 vessel head stud configuration. Specifically, the analytical model used in WCAP-16143 “Reactor Vessel Closure Head/Vessel Flange Requirements Evaluation for Byron/Braidwood Units 1 and 2” was based the original closure head configuration and did not represent the modified closure head configuration (53 head studs) applicable to the Unit 2 reactor vessel. The licensee entered this issue into their CAP as AR 01578276.

The inspectors determined that the performance deficiency was more than minor because it was associated with the Design Control attribute of the Barrier Integrity Cornerstone and adversely impacted the cornerstone objective of providing reasonable assurance that physical design barriers (fuel cladding, reactor coolant system, and containment) protect the public from radionuclide releases caused by accident or events. The inspectors also answered “yes” to the More-than-Minor screening question “If left uncorrected, would the performance deficiency have the potential to lead to a more significant safety concern?” Specifically, if left uncorrected, continued operation without a correct stress analysis to support the approved pressure temperature limit curves could have allowed the reactor to operate at a pressure and temperature that increased the chance for a brittle fracture of the vessel under a pressurized thermal shock event. The inspectors performed a Phase 1 Significance Determination Process Screening and selected the box under the Reactor Coolant System Boundary (e.g. pressurized thermal shock issues) which required a detailed risk evaluation. An NRC Region III senior reactor analyst performed a detailed risk evaluation of this finding. A potential increase in the probability for vessel failure would exist if the plant was operated in the unacceptable pressure-temperature regions and a pressurized thermal shock event occurred. Based on the licensee and supporting vendor assessments which concluded that no substantial increase in vessel stresses will occur due to operation with 53 head studs, the driving force for crack propagation (e.g. K1) will remain essentially unchanged. However, to bound the delta risk evaluation, it was assumed that the initiating event frequency for a reactor vessel failure increased by 10 percent. From the Byron Standardized Plant Analysis Risk model version 8.21, the initiating event frequency for reactor vessel failure from any cause was 1E-7/yr. Core damage is expected to occur if reactor vessel failure occurs. The exposure time for the finding was the maximum of one year. Thus, a bounding risk assessment yields a delta risk of 1E 8/yr. Therefore, based on the detailed risk evaluation, this finding is of very low risk significance. This finding has a cross-cutting aspect in the area of Human Performance Decision Making, because the licensee did not use conservative assumptions in decision making and adopt a requirement to demonstrate that the proposed action was safe in order to proceed. In this case, the licensee staff made a non-conservative assumption that the 10 CFR 50.59 process could be applied to authorize a change in the WCAP 16143 analysis and to not seek prior NRC approval (H.1 (b)).

Inspection Report# : [2013005](#) (*pdf*)

Significance:  Jun 30, 2013

Identified By: NRC

Item Type: NCV NonCited Violation

INACCURATE RISK ASSESSMENT

A finding of very low safety significance and an associated NCV of 10 CFR 50.65, "Requirements for Monitoring the Effectiveness of Maintenance at Nuclear Power Plants," was identified by the inspectors when licensee personnel removed both the 2B and 2D Reactor Containment Fan Coolers (RCFCs) from service without entering an elevated on-line risk status (Yellow) as required by licensee procedure WC-BY-101-1006, "On-Line Risk Management and Assessment." The licensee entered this issue into their Corrective Action Program (CAP) as Issue Report (IR) 01519964, "2B and 2D RCFC OLR [On-Line Risk] Not Communicated." As part of the licensee's corrective actions, on-line risk was revised to accurately reflect the removal of the 2B and 2D RCFCs from service.

The inspectors determined that the performance deficiency was more than minor because it was similar to IMC 0612, Appendix E, "Examples of Minor Issues," Example 7(e) that identified a failure to perform an adequate risk assessment when required by 10 CFR 50.65(a)(4) was not minor if the overall elevated plant risk placed the plant into a higher risk category established by the licensee. The inspectors determined the finding could be evaluated using the Significance Determination Process (SDP) in accordance with IMC 0609, Appendix K, "Maintenance Risk Assessment and Risk Management Significance Determination Process." In accordance with IMC 0609, Appendix K, and because the calculated Incremental Core Damage Probability Deficit (ICDPD) was not greater than 1E-6, the finding was determined to be of very low safety significance. This finding had a cross-cutting aspect in the Work Control component of the Human Performance cross-cutting area because coordination efforts between the departments responsible for evaluating and communicating on-line risk failed to identify and communicate a risk increase associated with maintenance on the 2B and 2D RCFCs (H.3.b).

Inspection Report# : [2013003](#) (*pdf*)

Emergency Preparedness

Occupational Radiation Safety

Public Radiation Safety

Security

Although the Security Cornerstone is included in the Reactor Oversight Process assessment program, the Commission has decided that specific information related to findings and performance indicators pertaining to the Security Cornerstone will not be publicly available to ensure that security information is not provided to a possible adversary. Other than the fact that a finding or performance indicator is Green or Greater-Than-Green, security related information will not be displayed on the public web page. Therefore, the [cover letters](#) to security inspection reports

may be viewed.

Miscellaneous

Last modified : February 24, 2014