


Browns Ferry 1

2Q/2012 Performance Indicators

Licensee's General Comments: none

Unplanned Scrams per 7000 Critical Hrs




Thresholds: White > 3.0 Yellow > 6.0 Red > 25.0

Notes

Unplanned Scrams per 7000 Critical Hrs	3Q/10	4Q/10	1Q/11	2Q/11	3Q/11	4Q/11	1Q/12	2Q/12
Unplanned scrams	0	0	0	1.0	0	0	0	0
Critical hours	2208.0	1475.8	2159.0	1646.9	2208.0	2105.9	2183.0	2184.0
Indicator value	0	0	0	0.9	0.9	0.9	0.9	0

Licensee Comments: none

Unplanned Power Changes per 7000 Critical Hrs




Thresholds: White > 6.0

Notes

Unplanned Power Changes per 7000 Critical Hrs	3Q/10	4Q/10	1Q/11	2Q/11	3Q/11	4Q/11	1Q/12	2Q/12
Unplanned power changes	0	1.0	0	0	2.0	1.0	0	1.0
Critical hours	2208.0	1475.8	2159.0	1646.9	2208.0	2105.9	2183.0	2184.0
Indicator value	0.8	1.7	1.7	0.9	2.8	2.6	2.6	3.2

Licensee Comments: none

Unplanned Scrams with Complications




Thresholds: White > 1.0

Notes

Unplanned Scrams with Complications	3Q/10	4Q/10	1Q/11	2Q/11	3Q/11	4Q/11	1Q/12	2Q/12
Scrams with complications	0	0	0	1.0	0	0	0	0
Indicator value	0.0	0.0	0.0	1.0	1.0	1.0	1.0	0.0

Licensee Comments: none

Safety System Functional Failures (BWR)



Thresholds: White > 6.0

Notes

Safety System Functional Failures (BWR)	3Q/10	4Q/10	1Q/11	2Q/11	3Q/11	4Q/11	1Q/12	2Q/12
Safety System Functional Failures	0	1	0	2	2	0	1	2
Indicator value	3	1	1	3	5	4	5	5

Licensee Comments:

2Q/12: LER 259/2012-006-00, High Pressure Coolant Injection System Turbine Failed to Trip Using the Manual Trip Pushbutton. The following LERs were identified as a result of the NFPA 805 Transition and are due to the same condition. In accordance with NEI 99-02 section 2.2, the following LERs count as single SSFF: LER 259/2012-001-00 - Unanalyzed Conditions Discovered During NFPA 805 Transition Review, LER 259/2012-002-00 - Fault Propagation During A Postulated Appendix R Event Could Result In An Inability To Close Motor Operated Valves, LER 259/2012-003-00 - Reactor Protection System Circuit Could Potentially Remain Energized During An Appendix R Fire, and LER 259/2012-004-00 - Fire Damage to Cables in Fire Areas Could Cause a Residual Heat Removal Service Water Pump to Spuriously Start.


1Q/12: LER 259/2011-008-01, High Vibrations on High Pressure Coolant Injection Booster Pump Thrust Bearings

3Q/11: LER 259/2011-003-00, Loss of Safety Function (SDC) Resulting from Emergency Diesel Generator Output Breaker Trip LER 259/2011-006-00, Loss of Safety Function (HPCI) Due to Primary Containment Isolation

2Q/11: LER 259/2010-003-01, Failure of a Low Pressure Coolant Injection Flow Control Valve LER 259/2011-002-00, Loss of Safety Function (SDC) Resulting from Loss of Power from C EDG Due to Oil Leak

4Q/10: LER 259/2010-001-00 (Units 1, 2, 3) - Unit 1, 2, and 3 Appendix R Safe Shutdown Instruction Procedures Contain Incorrect Operator Manual Actions

Mitigating Systems Performance Index, Emergency AC Power System



Thresholds: White > 1.00E-6 Yellow > 1.00E-5 Red > 1.00E-4

Notes

Mitigating Systems Performance Index, Emergency AC Power System	3Q/10	4Q/10	1Q/11	2Q/11	3Q/11	4Q/11	1Q/12	2Q/12
UAI (Δ CDF)	1.68E-07	7.59E-08	6.18E-08	5.65E-08	1.18E-07	7.42E-08	-2.06E-08	-3.16E-08
URI (Δ CDF)	-2.81E-07	-1.74E-07	-2.59E-07	5.84E-07	7.25E-07	7.25E-07	7.87E-07	8.15E-07
PLE	NO	NO	NO	NO	NO	NO	NO	NO
Indicator value	-1.10E-07	-9.80E-08	-2.00E-07	6.40E-07	8.40E-07	8.00E-07	7.70E-07	7.80E-07

Licensee Comments:

2Q/12: Risk Cap Invoked. Changed PRA Parameter(s). The MSPI Risk Cap is invoked. The contribution from one Failure to Run ($1.05E-06$) has been replaced by a value of $5.00E-07$. The D Diesel Generator Baseline Planned Unavailability was adjusted to reflect the 12-Year Diesel Maintenance Outages scheduled to be performed in the second quarter of 2012 (FAQ 468).

1Q/12: Risk Cap Invoked. Changed PRA Parameter(s). The MSPI Risk Cap is invoked. The contribution from one Failure to Run ($1.03E-06$) has been replaced by a value of $5.00E-07$. Revised PRA parameters based on Calculation NDN-000-999-2010-0003 rev 006 to reflect CAFTA PRA Model Revision 4. CAFTA PRA Model Revision 4 was performed in accordance with NEI 99-02 to evaluate the impacts of adjusting the Diesel Generator Baseline Planned Unavailability in conjunction with the 12-Year Diesel Maintenance Outages (FAQ 468). The B and C Diesel Generator Baseline Planned Unavailability was adjusted to reflect the 12-Year Diesel Maintenance Outages scheduled to be performed in the first quarter of 2012 (FAQ 468). Revised Emergency Diesel Generator run hours to exclude the run hours associated with (1) the first hour of run time after breaker closure and (2) unloaded run hours (FAQ 480). Revised Emergency Diesel Generator supercomponent boundary to include fuel oil transfer pumps/valves (FAQ 484).

4Q/11: Risk Cap Invoked. The MSPI Risk Cap is invoked. The contribution from one Failure to Run ($8.76E-07$) has been replaced by a value of $5.00E-07$. Problem Evaluation Report 439980 documented that D DG Failure was incorrectly classified as a Start Failure in EPIX Report 624 associated with Heat Exchanger Fouling. Based on the Past Operability performed on D DG, it was determined that the failure of the DG would have been a load-run failure. This failure classification does not result in a significant impact to MSPI calculations.

3Q/11: Risk Cap Invoked. Changed PRA Parameter(s). Revised MSPI Basis Document and MSPI PRA Parameters based on Calculation NDN-000-999-2010-0003 Rev 005 to reflect BFN CAFTA PRA Model Rev 3 which was approved in June 2011. MSPI PRA Parameters based on this model are effective as of Third Quarter 2011. The MSPI Risk Cap is also invoked. The contribution from one Failure to Run ($8.76E-07$) has been replaced by a value of $5.00E-07$.

3Q/11: Risk Cap Invoked. Revised MSPI Basis Document and MSPI PRA Parameters based on Calculation NDN-000-999-2010-0003 Rev 005 to reflect BFN CAFTA PRA Model Rev 3 which was approved in June 2011. MSPI PRA Parameters based on this model are effective as of Third Quarter 2011. The MSPI Risk Cap is also invoked. The contribution from one Failure to Run ($8.76E-07$) has been replaced by a value of $5.00E-07$. Problem Evaluation Report 439980 documented that D DG Failure was incorrectly classified as a Start Failure in EPIX Report 624 associated with Heat Exchanger Fouling. Based on the Past Operability performed on D DG, it was determined that the failure of the DG would have been a load-run failure. This failure classification does not result in a significant impact to MSPI calculations.

2Q/11: Revised MSPI Basis Document and MSPI PRA Parameters based on Calculation NDN-000-999-2010-0003 rev 003 to correct PRA Model errors associated with the modeling of EECW (Cooling Water System 2) North Header Unavailability and not modeling a failure of a normally operating EECW pump to restart following loss of offsite power. These changes are effective as of Second Quarter 2011.

2Q/11: Revised MSPI Basis Document and MSPI PRA Parameters based on Calculation NDN-000-999-2010-0003 rev 003 to correct PRA Model errors associated with the modeling of EECW (Cooling Water System 2) North Header Unavailability and not modeling a failure of a normally operating EECW pump to restart following loss of offsite power. These changes are effective as of Second Quarter 2011. Problem Evaluation Report 439980 documented that D DG Failure was incorrectly classified as a Start Failure in EPIX Report 624 associated with Heat Exchanger Fouling. Based on the Past Operability performed on D DG, it was determined that the failure of the DG would have been a load-run failure. This failure classification does not result in a significant impact to MSPI calculations.


1Q/11: Problem Evaluation Report 439980 documented that D DG Failure was incorrectly classified as a Start Failure in EPIX Report 624 associated with Heat Exchanger Fouling. Based on the Past Operability performed on D DG, it was determined that the failure of the DG would have been a load-run failure. This failure classification does not result in a significant impact to MSPI calculations.

4Q/10: Changed PRA Parameter(s). In September 2010, Revision 2 of the Browns Ferry CAFTA PRA Model became the model of record. All MSPI Parameters have been updated to reflect Revision 2 of the PRA model effective October 2010.

4Q/10: In September 2010, Revision 2 of the Browns Ferry CAFTA PRA Model became the model of record. All MSPI Parameters have been updated to reflect Revision 2 of the PRA model effective October 2010. Problem Evaluation Report 439980 documented that D DG Failure was incorrectly classified as a Start Failure in EPIX Report 624 associated with Heat Exchanger Fouling. Based on the Past Operability performed on D DG, it was determined that the failure of the DG would have been a load-run failure. This failure classification does not result in a significant impact to MSPI calculations.

3Q/10: Problem Evaluation Report 439980 documented that D DG Failure was incorrectly classified as a Start Failure in EPIX Report 624 associated with Heat Exchanger Fouling. Based on the Past Operability performed on D DG, it was determined that the failure of the DG would have been a load-run failure. This failure classification does not result in a significant impact to MSPI calculations.

Mitigating Systems Performance Index, High Pressure Injection System



Thresholds: White > 1.00E-6 Yellow > 1.00E-5 Red > 1.00E-4

Notes

Mitigating Systems Performance Index, High Pressure Injection System	3Q/10	4Q/10	1Q/11	2Q/11	3Q/11	4Q/11	1Q/12	2Q/12
UAI (ΔCDF)	5.38E-07	3.49E-07	3.33E-07	2.07E-07	3.20E-07	3.04E-07	3.92E-07	4.76E-07
URI (ΔCDF)	1.60E-07	1.01E-07	1.00E-07	4.72E-07	5.91E-07	5.90E-07	5.52E-07	7.26E-07
PLE	NO							
Indicator value	7.00E-07	4.50E-07	4.30E-07	6.80E-07	9.10E-07	8.90E-07	9.40E-07	1.20E-06

Licensee Comments:

2Q/12: The unit 1 HPCI system changed from green to white this quarter. There are 4 failures currently counted against HPCI (reports #527, #678, #701, #819) and excessive unavailability due to steam admission valve leakage.

1Q/12: Changed PRA Parameter(s). Revised PRA parameters based on Calculation NDN-000-999-2010-0003 rev 006 to reflect CAFTA PRA Model Revision 4. CAFTA PRA Model Revision 4 was performed in accordance with NEI 99-02 to evaluate the impacts of adjusting the Diesel Generator Baseline Planned Unavailability in conjunction with the 12-Year Diesel Maintenance Outages (FAQ 468). 4/12 Revised unplanned unavailability in May 2011 to count from point of discovery. This is a reduction in unplanned unavailability of about 17 hours.

3Q/11: Revised MSPI Basis Document and MSPI PRA Parameters based on Calculation NDN-000-999-2010-0003 Rev 005 to reflect BFN CAFTA PRA Model Rev 3 which was approved in June 2011. MSPI PRA Parameters based on this model are effective as of Third Quarter 2011.

3Q/11: Changed PRA Parameter(s). Revised MSPI Basis Document and MSPI PRA Parameters based on Calculation NDN-000-999-2010-0003 Rev 005 to reflect BFN CAFTA PRA Model Rev 3 which was approved in June 2011. MSPI PRA Parameters based on this model are effective as of Third Quarter 2011.

2Q/11: Unpl Unav resulted from discharge check valve hanging open, causing pump suction overpressure event, causing external leakage, which caused DC motor on aux oil pump to fail. See report #678.

2Q/11: Unplanned Unavailability resulted from discharge check valve hanging open, causing pump suction


overpressure event, causing external leakage, which caused DC motor on aux oil pump to fail. See report #678. Revised MSPI Basis Document and MSPI PRA Parameters based on Calculation NDN-000-999-2010-0003 rev 003 to correct PRA Model errors associated with the modeling of EECW (Cooling Water System 2) North Header Unavailability and not modeling a failure of a normally operating EECW pump to restart following loss of offsite power. These changes are effective as of Second Quarter 2011. 4/12 Revised unplanned unavailability to count from point of discovery of the failure. This was a reduction of about 17 hours.

2Q/11: Unplanned Unavailability resulted from discharge check valve hanging open, causing pump suction overpressure event, causing external leakage, which caused DC motor on aux oil pump to fail. See report #678. Revised MSPI Basis Document and MSPI PRA Parameters based on Calculation NDN-000-999-2010-0003 rev 003 to correct PRA Model errors associated with the modeling of EECW (Cooling Water System 2) North Header Unavailability and not modeling a failure of a normally operating EECW pump to restart following loss of offsite power. These changes are effective as of Second Quarter 2011.

4Q/10: Changed PRA Parameter(s). In September 2010, Revision 2 of the Browns Ferry CAFTA PRA Model became the model of record. All MSPI Parameters have been updated to reflect Revision 2 of the PRA model effective October 2010.

3Q/10: HPCI and RCIC operational demands changed to estimates from actuals for all 3 units.

Mitigating Systems Performance Index, Heat Removal System



Thresholds: White > 1.00E-6 Yellow > 1.00E-5 Red > 1.00E-4

Notes

Mitigating Systems Performance Index, Heat Removal System	3Q/10	4Q/10	1Q/11	2Q/11	3Q/11	4Q/11	1Q/12	2Q/12
UAI (ΔCDF)	6.22E-08	3.16E-08	6.29E-08	5.82E-08	6.66E-08	1.50E-08	1.35E-08	1.36E-08
URI (ΔCDF)	1.42E-07	1.19E-07	1.17E-07	1.15E-07	8.24E-08	-3.34E-08	-3.26E-08	-3.31E-08
PLE	NO	NO	NO	NO	NO	NO	NO	NO
	2.00E-	1.50E-	1.80E-	1.70E-	1.50E-	-1.80E-	-1.90E-	-2.00E-

Licensee Comments:

1Q/12: Changed PRA Parameter(s). Revised PRA parameters based on Calculation NDN-000-999-2010-0003 rev 006 to reflect CAFTA PRA Model Revision 4. CAFTA PRA Model Revision 4 was performed in accordance with NEI 99-02 to evaluate the impacts of adjusting the Diesel Generator Baseline Planned Unavailability in conjunction with the 12-Year Diesel Maintenance Outages (FAQ 468).

3Q/11: Changed PRA Parameter(s). Revised MSPI Basis Document and MSPI PRA Parameters based on Calculation NDN-000-999-2010-0003 Rev 005 to reflect BFN CAFTA PRA Model Rev 3 which was approved in June 2011. MSPI PRA Parameters based on this model are effective as of Third Quarter 2011.

2Q/11: Revised MSPI Basis Document and MSPI PRA Parameters based on Calculation NDN-000-999-2010-0003 rev 003 to correct PRA Model errors associated with the modeling of EECW (Cooling Water System 2) North Header Unavailability and not modeling a failure of a normally operating EECW pump to restart following loss of offsite power. These changes are effective as of Second Quarter 2011.


1Q/11: Changed PRA Parameter(s).

1Q/11: Unit 1 RCIC Baseline Performance Data was revised effective January 2011 to reflect actual Unit 1 RCIC performance from October 2007 through September 2010. Previously, Unit 2 RCIC Baseline Performance Data was used for Unit 1 RCIC because Unit 1 lacked sufficient operating history to develop a 12 quarter performance baseline.

4Q/10: Changed PRA Parameter(s). In September 2010, Revision 2 of the Browns Ferry CAFTA PRA Model became the model of record. All MSPI Parameters have been updated to reflect Revision 2 of the PRA model effective October 2010.

3Q/10: HPCI and RCIC operational demands changed to estimates from actuals for all 3 units.

Mitigating Systems Performance Index, Residual Heat Removal System



Thresholds: White > 1.00E-6 Yellow > 1.00E-5 Red > 1.00E-4

Notes

Mitigating Systems Performance Index, Residual Heat Removal System	3Q/10	4Q/10	1Q/11	2Q/11	3Q/11	4Q/11	1Q/12	2Q/12
UAI (Δ CDF)	2.26E-08	1.77E-09	1.90E-09	1.80E-09	3.08E-09	2.59E-09	1.04E-09	5.91E-09
URI (Δ CDF)	-1.76E-07	-5.62E-08	-5.66E-08	-5.65E-08	-3.08E-08	-2.94E-08	-2.80E-08	-2.83E-08
PLE	NO							
Indicator value	-1.50E-07	-5.40E-08	-5.50E-08	-5.50E-08	-2.80E-08	-2.70E-08	-2.70E-08	-2.20E-08

Licensee Comments:

1Q/12: Changed PRA Parameter(s). Revised PRA parameters based on Calculation NDN-000-999-2010-0003 rev 006 to reflect CAFTA PRA Model Revision 4. CAFTA PRA Model Revision 4 was performed in accordance with NEI 99-02 to evaluate the impacts of adjusting the Diesel Generator Baseline Planned Unavailability in conjunction with the 12-Year Diesel Maintenance Outages (FAQ 468).


3Q/11: Changed PRA Parameter(s). Revised MSPI Basis Document and MSPI PRA Parameters based on Calculation NDN-000-999-2010-0003 Rev 005 to reflect BFN CAFTA PRA Model Rev 3 which was approved in June 2011. MSPI PRA Parameters based on this model are effective as of Third Quarter 2011.

2Q/11: Revised MSPI Basis Document and MSPI PRA Parameters based on Calculation NDN-000-999-2010-0003 rev 003 to correct PRA Model errors associated with the modeling of EECW (Cooling Water System 2) North Header Unavailability and not modeling a failure of a normally operating EECW pump to restart following loss of offsite power. These changes are effective as of Second Quarter 2011.

4Q/10: Changed PRA Parameter(s). In September 2010, Revision 2 of the Browns Ferry CAFTA PRA Model became the model of record. All MSPI Parameters have been updated to reflect Revision 2 of the PRA model effective October 2010.

3Q/10: RHR operational demands and test demands changed to estimates from actuals for all 3 units.

Mitigating Systems Performance Index, Cooling Water Systems



Thresholds: White > 1.00E-6 Yellow > 1.00E-5 Red > 1.00E-4

Notes

Mitigating Systems Performance Index, Cooling Water Systems	3Q/10	4Q/10	1Q/11	2Q/11	3Q/11	4Q/11	1Q/12	2Q/12
UAI (Δ CDF)	5.35E-08	3.46E-09	3.46E-09	2.84E-09	2.62E-07	2.76E-07	2.18E-07	1.60E-07
URI (Δ CDF)	-1.14E-08	1.86E-08	1.86E-08	8.99E-09	-6.93E-08	-6.93E-08	-6.66E-08	-6.66E-08
PLE	NO	NO	NO	NO	NO	NO	NO	NO
Indicator value	4.20E-08	2.20E-08	2.20E-08	1.20E-08	1.90E-07	2.10E-07	1.50E-07	9.30E-08

Licensee Comments:

1Q/12: Changed PRA Parameter(s). Revised PRA parameters based on Calculation NDN-000-999-2010-0003 rev 006 to reflect CAFTA PRA Model Revision 4. CAFTA PRA Model Revision 4 was performed in accordance with NEI 99-02 to evaluate the impacts of adjusting the Diesel Generator Baseline Planned Unavailability in conjunction with the 12-Year Diesel Maintenance Outages (FAQ 468).

3Q/11: Revised MSPI Basis Document and MSPI PRA Parameters based on Calculation NDN-000-999-2010-0003 Rev 005 to reflect BFN CAFTA PRA Model Rev 3 which was approved in June 2011. MSPI PRA Parameters based on this model are effective as of Third Quarter 2011. Problem Evaluation Report 468993 documents changes to RHRSW pump demand failures to run failures on failure reports 573, 584, and 692.

3Q/11: Changed PRA Parameter(s). Revised MSPI Basis Document and MSPI PRA Parameters based on Calculation NDN-000-999-2010-0003 Rev 005 to reflect BFN CAFTA PRA Model Rev 3 which was approved in June 2011. MSPI PRA Parameters based on this model are effective as of Third Quarter 2011.


2Q/11: Revised MSPI Basis Document and MSPI PRA Parameters based on Calculation NDN-000-999-2010-0003 rev 003 to correct PRA Model errors associated with the modeling of EECW (Cooling Water System 2) North Header Unavailability and not modeling a failure of a normally operating EECW pump to restart following loss of offsite power. These changes are effective as of Second Quarter 2011. Problem Evaluation Report 468993 documents changes to RHRSW pump demand failures to run failures on failure reports 573, 584, and 692.

2Q/11: Revised MSPI Basis Document and MSPI PRA Parameters based on Calculation NDN-000-999-2010-0003

System Activity	7/11	8/11	9/11	10/11	11/11	12/11	1/12	2/12	3/12	4/12	5/12	6/12
Maximum activity	0.000077	0.000079	0.000083	0.000085	0.000096	0.000089	0.000161	0.000174	0.000172	0.000100	0.000177	0.000185
Technical specification limit	3.2	3.2	3.2	3.2	3.2	3.2	3.2	3.2	3.2	3.2	3.2	3.2
Indicator value	0	0	0	0	0	0	0	0	0	0	0	0

Licensee Comments: none

Reactor Coolant System Leakage




Thresholds: White > 50.0 Yellow > 100.0

Notes

Reactor Coolant System Leakage	7/10	8/10	9/10	10/10	11/10	12/10	1/11	2/11	3/11	4/11	5/11	6/11
Maximum leakage	2.080	2.080	2.600	2.070	2.110	2.150	2.170	2.230	2.220	2.170	2.230	2.600
Technical specification limit	30.0	30.0	30.0	30.0	30.0	30.0	30.0	30.0	30.0	30.0	30.0	30.0
Indicator value	6.9	6.9	8.7	6.9	7.0	7.2	7.2	7.4	7.4	7.2	7.4	8.7
Reactor Coolant System Leakage	7/11	8/11	9/11	10/11	11/11	12/11	1/12	2/12	3/12	4/12	5/12	6/12
Maximum leakage	2.730	2.780	2.890	3.170	3.470	3.560	2.230	2.940	2.060	2.290	2.390	2.210
Technical specification limit	30.0	30.0	30.0	30.0	30.0	30.0	30.0	30.0	30.0	30.0	30.0	30.0
Indicator value	9.1	9.3	9.6	10.6	11.6	11.9	7.4	9.8	6.9	7.6	8.0	7.4

Licensee Comments: none

Drill/Exercise Performance




Thresholds: White < 90.0% Yellow < 70.0%

Notes

Drill/Exercise Performance	3Q/10	4Q/10	1Q/11	2Q/11	3Q/11	4Q/11	1Q/12	2Q/12
Successful opportunities	50.0	39.0	25.0	24.0	37.0	111.0	13.0	6.0
Total opportunities	50.0	40.0	26.0	24.0	38.0	112.0	13.0	6.0
Indicator value	98.5%	98.5%	98.1%	98.3%	98.1%	98.4%	98.7%	98.7%

Licensee Comments: none

ERO Drill Participation




Thresholds: White < 80.0% Yellow < 60.0%

Notes

ERO Drill Participation	3Q/10	4Q/10	1Q/11	2Q/11	3Q/11	4Q/11	1Q/12	2Q/12
Participating Key personnel	73.0	74.0	76.0	77.0	72.0	80.0	74.0	73.0
Total Key personnel	73.0	74.0	77.0	79.0	75.0	80.0	74.0	73.0
Indicator value	100.0%	100.0%	98.7%	97.5%	96.0%	100.0%	100.0%	100.0%

Licensee Comments: none

Alert & Notification System



Thresholds: White < 94.0% Yellow < 90.0%


Notes

Alert & Notification System	3Q/10	4Q/10	1Q/11	2Q/11	3Q/11	4Q/11	1Q/12	2Q/12
Successful siren-tests	898	699	700	599	896	799	800	799
Total sirens-tests	900	700	700	600	900	800	800	800
Indicator value	99.6%	99.6%	99.7%	99.9%	99.8%	99.8%	99.8%	99.8%

Licensee Comments:

2Q/11: Siren Test canceled for May 9, 2011 due to severe weather in the area.

Occupational Exposure Control Effectiveness




Thresholds: White > 2.0 Yellow > 5.0

Notes

Occupational Exposure Control Effectiveness	3Q/10	4Q/10	1Q/11	2Q/11	3Q/11	4Q/11	1Q/12	2Q/12
High radiation area occurrences	1	0	0	0	0	0	0	0
Very high radiation area occurrences	0	0	0	0	0	0	0	0
Unintended exposure occurrences	0	0	0	0	0	0	0	0
Indicator value	1	1	1	1	0	0	0	0

Licensee Comments: none

RETS/ODCM Radiological Effluent



Thresholds: White > 1.0 Yellow > 3.0

Notes

RETS/ODCM Radiological Effluent	3Q/10	4Q/10	1Q/11	2Q/11	3Q/11	4Q/11	1Q/12	2Q/12
RETS/ODCM occurrences	0	0	0	0	0	0	0	0
Indicator value	0	0	0	0	0	0	0	0

Licensee Comments: none

Although the Security Cornerstone is included in the Reactor Oversight Process assessment program, the Commission has decided that specific information related to findings and performance indicators pertaining to the Security Cornerstone will not be publicly available to ensure that security information is not provided to a possible adversary. Other than the fact that a finding or performance indicator is Green or Greater-Than-Green, security related information will not be displayed on the public web page.
