

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 8

National Average: 46

2x National Average: 92

National Median: 23

Average for Selected Dockets: 8

Facility Name: Seabrook 1 Docket (050- 00443)

Details**Human-System Interface & Environmnt / IR**

170 - HSI or information availability / quality LTA

Department

Q - Quality assurance / oversight

Work Type

M - Maintenance / Repair

Docket/Report

050-00443/2009-007

Number of Items for this Docket: 1**Percent of Total for this Docket:** 13**Problem Identification & Resolution / IR**

145 - Causal development LTA

S - Specialized task force

W - Assessment

050-00443/2009-007

Number of Items for this Docket: 1**Percent of Total for this Docket:** 13**Work Planning & Practices / IR**

186 - Failure to take action / meet requirements

M - Mechanical

V - Troubleshooting

050-00443/2009-004

186 - Failure to take action / meet requirements

M - Mechanical

F - Modification

050-00443/2009-004

186 - Failure to take action / meet requirements

G - Engineering

G - Design

050-00443/2009-007

186 - Failure to take action / meet requirements

M - Mechanical

M - Maintenance / Repair

050-00443/2009-007

187 - Action implementation LTA

G - Engineering

G - Design

050-00443/2009-004

187 - Action implementation LTA

G - Engineering

G - Design

050-00443/2009-007

Number of Items for this Docket: 6**Percent of Total for this Docket:** 75**Total Items for this Docket:** 8